

## Test Report

No. CANEC1818312902

Date: 11 Sep 2018

Page 1 of 4

3M MATERIAL TECHNOLOGY (GUANGZHOU) CO.,LTD.

NO.9,NANXIANG 2 ROAD,SCIENCE CITY GUANGZHOU HIGH TECH INDUSTRY DEVELOPMENT DISTRICT  
CHINA

The following sample(s) was/were submitted and identified on behalf of the clients as : 7613T

SGS Job No. : CP18-049269 - GZ  
Model No. : 7613T  
Client Ref. Info. : 3690E, 7600  
Date of Sample Received : 04 Sep 2018  
Testing Period : 04 Sep 2018 - 11 Sep 2018  
Test Requested : Selected test(s) as requested by client.  
Test Method : Please refer to next page(s).  
Test Results : Please refer to next page(s).

Signed for and on behalf of  
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Zmguan

Zm guan  
Approved Signatory



# Test Report

No. CANEC1818312902

Date: 11 Sep 2018

Page 2 of 4

Test Results :

Test Part Description :

Specimen No.	SGS Sample ID	Description
SN1	CAN18-183129.001	White adhesive sheet

Remarks :

- (1) 1 mg/kg = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected ( < MDL )
- (4) "-" = Not Regulated

**Halogen**

Test Method : With reference to EN 14582:2016, analysis was performed by IC.

<u>Test Item(s)</u>	<u>Unit</u>	<u>MDL</u>	<u>001</u>
Fluorine (F)	mg/kg	50	ND
Chlorine (Cl)	mg/kg	50	134738
Bromine (Br)	mg/kg	50	ND
Iodine (I)	mg/kg	50	ND


Remark: Result of Cl is only for reference.




ATTACHMENTS

Halogen Testing Flow Chart

- 1) Name of the person who made testing: Bruce Xiao
- 2) Name of the person in charge of testing: Bella Wang



Sample photo:



SGS authenticate the photo on original report only

\*\*\* End of Report \*\*\*